

2018 GM IOB Update

All 2018 GM vehicles require an update.

- 1: Download the Zip File to your computer.
- 2: Unzip the file, there will be 3 files in-side of the Zip file.
- 3: Copy the files to the root directory of a blank formatted USB drive (1GB Min). Copy the 3 files, not the directory.
- 4: Install the Interface completely but leave the module where you can access it.
- 5: Plug the USB stick into the USB port on the module.
- 6: Turn on the vehicle ignition and the update will start automatically. Let it run. It takes about 10 min's.
- 7: After 10 min's. make sure the light on the USB drive is not flashing any longer. Shut off the vehicle and remove the USB drive.
- 8: Restart the vehicle.
- 9: If the vehicle has a factory rear camera move on to the step below.

Vehicles equipped w/Factory Rear Camera

In order for the interface to work properly on vehicles equipped with the factory rear view camera, in addition to updating the interface, you have to cut the green/white wire pin 2 in the grey plug found in the rear of the factory display.

NOTE: Cut the wire back far enough in-case you need to re-connect at a later date. Tape both sides of the wire after cutting.

