



# INSTALLATION CHANGE NOTICE

**Effects part# 250-8450 and 250-8451**

2017 Chevrolet, Buick, and GMC vehicles are now equipped with a new WiFi enabled Radio. The new radio requires a change to the method of installation from what is currently shown in the included manual.

This change is effective for **vehicles with or without this WiFi system** and is backward compatible with earlier year vehicles.

**NOTE: Not Compatible with vehicles with RSE.**

- 1: DO NOT connect the video LVDS cable at the HMI module.**
- 2: Use the enclosed new video cables and connect to the video at the rear of the screen on the dash panels shown below.
- 3: Route the cable to the Interface module and connect to the appropriate ports. **NOTE: The Cables are labeled and MUST be connected correctly or no video will show.**
- 4: There are no other changes required.
- 5: Follow all other current installation instructions.

8" Mylink Dash Panel



Connection Point

